

Marlborough Vintage Car Club

Contact: Tris Winstanley

email: tandhwin@xtra.co.nz

Camshafts

5/9/2025

Vehicle	Qty	Cylinders	Casting Numbers	Details
Chev - model unknown	1	6		reground
Chev 1929-31	3	6	835507 3762	fuel pump cam near front
Chev 316cu in 1938-53	4	6	838733	fuel pump cam near front
Dodge ??	1	6	DB14	
Dodge & Plymouth truck 1935-40	2	6	601266 CWC 33 F11	fuel pump cam near front
Ford	1	4	F4 K29T	
Ford	1	4	H13	
Ford 105E	2	4	MC24135 109E	
Ford 109E	1	4	MC24136 11 N R 2A	fuel pump cam near rear
Ford Cortina	1	4	771M-8250-OA R85	needs regrind
Ford Mk2 Consul or Zephyr 4	1	4	70-HM-8250-AD	New
Ford V8 60 HP 1937-40	1	8	3	alloy timing gear
Ford V8 85&95 HP 1932-41	2	8	5T	alloy timing gear
Hudson Terraplane	1	6	182644 K29	fuel pump cam near front
Mazda 1800	1	4	453 (.012)	new
PB Vauxhall	1	6		reconditioned
Plymouth 1928-29	1	6		
Pontiac 1936	1	6		
Singer 1930's OHC	1	4		sprocket drive
Standard 8/10 up to 1957	1	4	201326	fuel pump cam near rear
Studebaker Commander 1947-60	1	6	L/30 CWC 523682	
Studebaker Dictator 1936-37. Studebaker Commander 1938-40	1	6	187223	
Triumph Herald 948/1200	1	4	204490MC	fuel pump cam near rear
Valiant Charger V8	1	8		new
Vauxhall Velox 1952-56	2	6	11863HI 7107212 JGGB	reconditioned - fuel pump cam near rear

Unknown	1	4		reground - fuel pump cam near front
Unknown	2	4	LN12	fuel pump cam near front
Unknown	1	4	MG MS79	
Unknown	1	4	MTL 4140	
Unknown	2	4	HN8	fuel pump cam near front
Unknown	1	4		fuel pump cam near front
Unknown	1	4	1206031 M V	fuel pump cam near rear
Unknown	1	4	ENG	fuel pump cam near front
Unknown	3	4	PE21	fuel pump cam near front
Unknown	1	6		Kelford Cams
Unknown	1	6	527119	fuel pump cam near front
Unknown	1	6	D18 43803 4 CWC	fuel pump cam near front
Unknown	1	6		fuel pump cam near front
Unknown	1	6	2938	fuel pump cam near front
Unknown	1	6	74751	fuel pump cam near front
Unknown	1	6		

